PRELIMINARY SUMMARY OF MAP ACTIONS

Community: DUBOIS COUNTY Community No: 180054

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	95-05-2136A	09/18/1995	5940 W. PORTERSVILLE ROAD WEST	1800540001A	18037C0125D
LOMA	02-05-4243A	09/06/2002	PART OF NW 1/4 OF SW 1/4 OF SECT. 9, TWP. 1 S, RANGE 4 W; 4246 NORTH 175 EAST	1800540002A	18037C0175D
LOMA	02-05-3742A	11/06/2002	ST. ANTHONY QUADRANGLE, NE1/4 SE1/4 SW1/4 SEC 17, T3S, R3W; 8865 S. SCHNELL RD.	1800540009A	18037C0275D
LOMA	06-05-BH32A	07/25/2006	1376 WEST COUNTY ROAD 400 NORTH PORTION OF SECTION 1, T1S, R5W (IN)	1800540002A	18037C0135D
LOMA	07-05-1784A	02/13/2007	6570 NORTH 1050 EAST PORTION OF SECTION 35, T1N, R3W (IN)	1800540003A	18037C0200D
LOMA	07-05-6286A	01/10/2008	PORTION OF SECTION 13, T1S, R5W 240 WEST 400 NORTH	1800540002A	18037C0141D
LOMA	11-05-0066A	12/09/2010	4890 SOUTH CLUB ROAD	1800540005A	18037C0275D

9/23/2011 Page 1 of 2

PRELIMINARY SUMMARY OF MAP ACTIONS

Community: DUBOIS COUNTY Community No: 180054

3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

- 1. Insufficient information available to make a determination.
- 2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
- 3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
- 4. Revised hydrologic and hydraulic analyses.
- 5. Revised topographic information.

4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

9/23/2011 Page 2 of 2